

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/16/2017

Submitted Date:

05/18/2017

Document Number:

668005441

FIELD INSPECTION FORM

Loc ID 425146 Inspector Name: DURAN, JOHN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10417
Name of Operator: INCREMENTAL OIL & GAS (FLORENCE) LLC
Address: 600 17TH ST SUITE 2625 SOUTH
City: DENVER State: CO Zip: 80202

Findings:

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Harkins, Liz	303-233-2232/719-429-4513	Lharkins@austinexploration.com	All Inspections
Goss, Aaron	303-233-2232/303-495-0327	AGoss@austinexploration.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
425132	WELL	PR	12/13/2011	OW	043-06209	Paiute 34-29	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign has been updated with current operator and emergency contact number.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Deadman # & Marked	# 4				
Ancillary equipment	# 1	Electrical box			
Pump Jack	# 1				
Emission Control Device	# 1				

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	300 BBLs	FIBERGLASS AST		,
Comment:	<input type="text"/>				

Corrective Action:	Date:
--------------------	-------

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 425132 Type: WELL API Number: 043-06209 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	425197	2215734	