

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/22/2017

Submitted Date:

05/22/2017

Document Number:

679902565**FIELD INSPECTION FORM**

Loc ID 337804 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 86610Name of Operator: CAERUS WASHCO LLCAddress: 1001 17TH STREET - STE #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Grant, Rachael	918-585-1650 ext 212	regulatory@foundationenergy.com	
McKee, Michael	720-880-6322	mmckee@caerusoilandgas.co	EHS (all Inspections)

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288722	WELL	PR	08/01/2008	GW	125-10611	KNODEL 22-16	PR

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Metal panels around meter sheds and VGS		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Sentry unit		
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:	Shared meter run for KNODEL 21-16, 22-16, 31-16 30' NW of wellhead		
Corrective Action:		Date:	
Type: Vertical Separator	# 3		
Comment:	3-Vertical gas separators 50% buried by meter sheds		
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Electric panel and telemetry equipment at meter sheds		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	288722	Type:	WELL	API Number:	125-10611	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Central meter run for (KNODEL 21-16, 22-16, 31-16) @ 39.71128/-102.07819								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401291058	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4153903">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4153903</a>