

Inspection Photos

Location Number: 331092



Photo 1 Wellhead from north



Photo 2 Separator from north

Inspection Photos



Photo 3 Unused risers by separator from southwest.



Photo 4 Tank Battery from northwest

Inspection Photos

Photo 5

Photo 6

