

# Inspection Photos

## Location Number: 310159



**Photo 1 Pressure chart inside pump house  
Inj Tubing 900 psi**



**Photo 2 Prime movers inside pump house  
1-175 HP and 1-165 HP**



# Inspection Photos



**Photo 3 tank battery and truck depot/drain from southwest**



**Photo 4 Well ID signage at wellhead from south**

# Inspection Photos



**Photo 5 Inj Tubing pressure gauge 800 PSI**



**Photo 6 Bradenhead pressure @ 0 psi**

# Inspection Photos



**Photo 7 Casing pressure at 0 PSI**