

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: 32 8N90W Central Battery
Facility ID: 450747



Photo 1. Overview of location taken at entrance facing north.



Photo 2. Overview of location taken at entrance facing northeast.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: 32 8N90W Central Battery
Facility ID: 450747



Photo 3. Riser cluster in center of location.



Photo 4. Produced water tank with risers.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: 32 8N90W Central Battery
Facility ID: 450747



Photo 5. Interior of compressor shed.



Photo 6. Compressor and ECD with flowlines.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: 32 8N90W Central Battery
Facility ID: 450747



Photo 7. Horizontal heated separator with risers.



Photo 8. Tank battery with animal burrows visible in berm.