

# Inspection Photos

## Location Number: 318164



**Photo 1 Wellhead from south**



**Photo 2 Battery signage from south**

# Inspection Photos



**Photo 3 Battery overview from southeast**



**Photo 4 Separation and Emission Control Burner from northwest**