



photo 1: Facing southeast along the access road which has not been reclaimed.



photo 2: Facing east at the location. The vegetation is beginning to establish.



photo 3: There are noxious weeds (Canada thistle) beginning to grow at the north side of the location.



photo 4: East side of the location facing west.