

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/31/2017

Submitted Date:

06/01/2017

Document Number:

675103649**FIELD INSPECTION FORM**

Loc ID 334347 Inspector Name: GRANAHAH, KYLE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Encana		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284301	WELL	PR	02/01/2007	GW	077-09051	RADEL 11-12 (OL11)	EG
284302	WELL	PR	01/07/2008	GW	077-09050	RADEL 10-9 (OL11)	EG
284303	WELL	PR	01/07/2008	GW	077-09049	RADEL 10-16(OL11)	EG

General Comment:2017 Flowline NTO inspection 1000' buffer

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Present/complete		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-625-4209

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	39.36201/-108.08506		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:	39.36201/-108.08506		
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	IN USE; 3-3" steel risers from wells to separators. 3-3" steel risers from gas out separator to sales line. 3-2" steel risers from separator water/oil dump to tank battery. 1 -3" steel riser from separator gas out to gas meter sales. 3-2" steel risers from separator water/oil dump to tank battery.		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chem tote with secondary containment		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		39.361960,-108.085410	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 284301 Type: WELL API Number: 077-09051 Status: PR Insp. Status: EG

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Well SI at time of inspection, bradenhead/well pressure remotely monitored

Corrective Action: Date:

Flowline

#1 Type: Well Site of Lines

Flowline Description

Flowline Type: Well Site Size: Material:

Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:

Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: IN USE; 3-3" steel risers from wells to separators. 3-3" steel risers from gas out separator to sales line. 3-2" steel risers from separator water/oil dump to tank battery. 1-3" steel riser from separator gas out to gas meter sales. 3-2" steel risers from separator water/oil dump to tank battery.

Corrective Action: Date:

Facility ID: 284302 Type: WELL API Number: 077-09050 Status: PR Insp. Status: EG

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Well SI at time of inspection, bradenhead/well pressure remotely monitored

Corrective Action: Date:

Facility ID: 284303 Type: WELL API Number: 077-09049 Status: PR Insp. Status: EG

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Well SI at time of inspection, bradenhead/well pressure remotely monitored

Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Berms	Pass					
Compaction	Pass					
Retention Ponds	Pass					

Comment: [No sediment flow evident](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401297951	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160334
675103652	flow line photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160321