

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/07/2017

Submitted Date:

06/08/2017

Document Number:

679700476**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
ALLISON, RICK 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Noble		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450999	SPILL OR RELEASE	AC	06/07/2017		-	Rouse USX AB 33-13	EI

General Comment:

[COGCC Environmental Inspection of Spill ID 450999 reported at the Rouse USX AB 33-13 tank battery](#)

Environmental**Spill/Remediation:**

Comment: Backfill of excavation in area of separators was nearly complete during COGCC site visit. No oily waste was stockpiled on the location. Supplement Form 19 Spill Detail Report is due 6/17/2017. Operator is also to report results of investigation via Form 19 (or Form 27 if groundwater is impacted), and to report a detailed root cause for the flowline failure with a corrective action to prevent future releases.

Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____

Wildlife Protection Devices (fired vessels): _____