



**photo 1:** Facing south toward the access road standing from the county road.



**photo 2:** There is an electric utility that remains along the access road which will need to be removed.





**photo 3:** Facing south toward the location. A portable facility remains at the location.



**photo 4:** West side of the location facing northeast. The location has not been reclaimed and a soil pile remains.





**photo 5:** Facing southeast toward the surrounding crop.