



photo 1: Facing west toward the beginning of the former access road.



photo 2: Facing west near the location along the access road. This area appears to have recently been reclaimed.



photo 3: Facing southwest toward the location which has been reclaimed.



photo 4: A pipe riser remains at the location, Lat/Long:39.93960,-104.71855.



photo 5: The pipe riser has been locked and tagged out.



photo 6: There are noxious weeds at the location (Scotch thistle).