



photo 1: Facing east along the former access road toward the location.



photo 2: There is a pipe riser at the tank battery site.



photo 3: There is no lock out/ tag out applied to this pipe riser.



photo 4: Facing east toward the location. The field is infested with noxious weeds (Scotch thistle). The weeds are tall and thick making the site inaccessible.