

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/14/2017

Submitted Date:

06/14/2017

Document Number:

666803236**FIELD INSPECTION FORM**

Loc ID 323783 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10550Name of Operator: MUSTANG RESOURCES LLCAddress: 1660 LINCOLN STREET SUITE 1450City: DENVER State: CO Zip: 80264**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Austin, Chris	970-756-1696	caustin@mustangresourcesllc.com	
Couts, Brandon		bcoutts@mustangresourcesllc.com	Field Operations

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210798	WELL	PR	12/01/2016	GW	045-06556	MEAD 23-44-6S-94W	PR

**General Comment:**2017 Flowline NTO Inspection 1000' Buffer

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run	# 1		
Comment:	39.506960/-107.850622		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	39.507365/-107.850358		
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	In use; 1-2" steel risers at wellhead, 3-2" risers at separators, 1-3" risers at tanks, 4-2" and 1-1" risers at gas meter run, 2-4", 3-2", 2-3" risers at compressor		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	39.506959/-107.850435		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	39.507433/-107.850298		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	39.509314/-107.850259		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLS	STEEL AST		39.507174,-107.850622
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	210798	Type:	WELL	API Number:	045-06556	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:				Date:					

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Gravel	Pass			
		Ditches	Pass			
		Culverts	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT