

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/15/2017

Submitted Date:

06/15/2017

Document Number:

666803240

**FIELD INSPECTION FORM**

Loc ID 323938 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

22 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	<a href="#">Field Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211305	WELL	PR	11/10/1996	GW	045-07064	ESTATE OF CLAUDE B HAMILL RMV-28-27	PR
418931	WELL	PR	02/17/2013	GW	045-19832	Savage RWF 34-27	PR
418932	WELL	PR	09/30/2012	GW	045-19833	Savage RWF 322-34	PR
418934	WELL	PR	02/17/2013	GW	045-19834	Savage RMV 80-34	PR
418935	WELL	PR	02/26/2013	GW	045-19835	Savage RWF 11-34	PR
418938	WELL	PR	09/30/2012	GW	045-19836	Savage RWF 22-34	PR
418943	WELL	PR	02/28/2013	GW	045-19838	Savage RWF 341-34	PR
418947	WELL	PR	02/26/2013	GW	045-19841	Savage RMV 86-34	PR
418948	WELL	PR	02/26/2013	GW	045-19842	Savage RWF 321-34	PR
418950	WELL	PR	03/15/2013	GW	045-19843	Savage RWF 41-34	PR
418951	WELL	PR	02/28/2013	GW	045-19844	Savage RWF 331-34	PR
418953	WELL	PR	09/30/2012	GW	045-19846	Savage RWF 31-34	PR
418954	WELL	PR	09/30/2012	GW	045-19847	Savage RWF 434-27	PR
418955	WELL	PR	02/17/2013	GW	045-19848	Savage RMV 103-27	PR
418958	WELL	PR	10/12/2012	GW	045-19849	Savage RMV 71-34	PR
418959	WELL	PR	03/05/2013	GW	045-19850	Savage RWF 344-27	PR

**General Comment:**

2017 Flowline NTO Inspection 1000' Buffer  
Shared central tank battery with location ID 335278.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type		#		corrective date
Type: Flow Line		#		
Comment:	In use; 16-2" steel risers at wellhead,			
Corrective Action:				Date:
Type: Ancillary equipment		# 2		
Comment:	Chemical units at wellhead			
Corrective Action:				Date:
Type: Plunger Lift		# 16		
Comment:	39.490250/-107.872476			
Corrective Action:				Date:

**Venting:**

Yes/No	YES		
Comment:	Bradenhead valves open		
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211305	Type:	WELL	API Number:	045-07064	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	418931	Type:	WELL	API Number:	045-19832	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	418932	Type:	WELL	API Number:	045-19833	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	418934	Type:	WELL	API Number:	045-19834	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	418935	Type:	WELL	API Number:	045-19835	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	418938	Type:	WELL	API Number:	045-19836	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	418943	Type:	WELL	API Number:	045-19838	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	418947	Type:	WELL	API Number:	045-19841	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				

Facility ID: 418948	Type: WELL	API Number: 045-19842	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				Date:
Corrective Action:				
Facility ID: 418950	Type: WELL	API Number: 045-19843	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				Date:
Corrective Action:				
Facility ID: 418951	Type: WELL	API Number: 045-19844	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				Date:
Corrective Action:				
Facility ID: 418953	Type: WELL	API Number: 045-19846	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				Date:
Corrective Action:				
Facility ID: 418954	Type: WELL	API Number: 045-19847	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				Date:
Corrective Action:				
Facility ID: 418955	Type: WELL	API Number: 045-19848	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				Date:
Corrective Action:				
Facility ID: 418958	Type: WELL	API Number: 045-19849	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				Date:
Corrective Action:				
Facility ID: 418959	Type: WELL	API Number: 045-19850	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				Date:
Corrective Action:				



**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Seeding	Pass					
		Ditches	Pass			
Sediment Traps	Pass					
Gravel	Pass					
Ditches	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT