



photo 1: The meter run remains at the former tank battery site. Lat/Long:39.82048,-104.36622



photo 2: There has been no lock out/tag out applied to the valve levers.



photo 3: Facing toward the gas meter run at the former tank battery site.
Lat/Long:39.82048,-104.36622



photo 4: Facing south toward the location. There has been no crop planted this season.