



photo 1: Facing west along the former access road to the location. The road has not been reclaimed and gravel remains.



photo 2: There are noxious weeds along the access road and at the location. (Musk thistle, Canada thistle)



photo 3: The gravel remains along the access road.



photo 4: Facing west along the access road. Noxious weeds are shown in the photo.



photo 5: Facing west at the location.



photo 6: There is a metal bar and wooden timber that remains at the location.