

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	TRENTON WEBBER (trenton.webber@bp.com)
Submission Date:	Jun 12, 2017 8:14:02 AM MDT
Server Receive Date:	Jun 12, 2017 8:15:12 AM MDT
Reference Number:	20170612-1861506933
Location:	Unknown Location

Information

Name	trenton.webber@bp.com
Date	Jun 9, 2017
Select Run	Florida Direct SE
Well Name	CUMMINS, LILA GAS UNIT A 2
API Number	50670881900
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean up Operator Debris Clean Up Contaminated Soils

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Completed work description

All erosional channels repaired, rock run down built.
Trash picked up. Cleaned up stained soil.

Notes

All items complete