



photo 1: There is equipment that remains at the location.



photo 2: The sign indicates Hosmer 4-9 Battery. The Hosmer 4-9 well was plugged and abandoned on 7/15/2015.



photo 3: This valve on the pipe line lever has lock out/tag out.



photo 4: Facing east toward the Hosmer 4-9 Battery.



photo 5: There are List B noxious weeds (Canada thistle) at the Hosmer 4-9 Battery.



photo 6: West side of the location facing southeast. There is an area of disturbance which has not been reclaimed.



photo 7: Facing east at the location and north of the Hosmer 4-9 Battery.



photo 8: There is a pipe riser at the location Lat/Long:39.90421,-10454758.



photo 9: The sign at the tank at Lat/Long:39.903918,-104.54584.