



**Inspected Facilities**

Facility ID: 210181 Type: WELL API Number: 045-05076 Status: DM Insp. Status: DM

**Workover**

Comment: June 6, 2017 Tuesday  
 PU 5-7/8 bit, XO, 4 4-1/16 drill collars, XO and XO to 2-3/8" tbg, RIH tag retainer and RU to Drill. Pumped drilling mud recovered from the well to circulate down tbg and taking returns to the cellar. Used a Vacuum truck to load fluid out of the cellar and return to the flat tank. Made about 1/2' in the 1st hr. Drilled to 4 pm without any discernable footage being made. Moved approximately 660 bbls from the cellar to the flat tank. POOH with tbg, Drill collars, Laid down bit which was still green. Sdf night.

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401306411	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4168588">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4168588</a>