

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/14/2017

Submitted Date:

06/16/2017

Document Number:

679902646**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
321219 \_\_\_\_\_ Welsh, Brian \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 56565Name of Operator: MERIT ENERGY COMPANYAddress: 13727 NOEL ROAD STE 1200City: DALLAS State: TX Zip: 75240**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Strachan, Steve	(303) 785-7006	sms@strachanexploration.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206326	WELL	PR	05/21/1977	GW	011-06072	STARK A 1	PA

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Dirt road through farm ground		
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Wire fence around tank		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe cage removed during cementing process		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Pipe fence around flowline riser		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:	East side of tank		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	210bbls
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 206326 Type: WELL API Number: 011-06072 Status: PR Insp. Status: PA**Cement**Cement ContractorContractor Name: Consolidated Well

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging OperationsDepth Plugs(feet range): 4450/969/380Cement Volume (sx): 290Good Return During Job: YESCement Type: Class A NEATComment:

Halde Water, Consolidated Well Service, Codell Well Service Rig #2. MIRU CODELL. RIH W/TBG TO 4575' TOF (Top Of Fish). MIRU CONSOLIDATED. PUMP 20SX CMT CSG PLUG W/3% CC. DISP W/15BBL WATER. MIRU CODELL. POOH W/20 STANDS OF TBG. WOC 2HRS. RIH W/TBG AND TAG CMT AT 4450'. POOH W/TBG. RIH W/15 STANDS AND SET RETAINER AT 969'. MIRU CONSOLIDATED. PUMP 120SX CMT THROUGH RETAINER. MIRU CODELL. STING OUT OF RETAINER. MIRU CONSOLIDATED. PUMP 35SX CMT ON TOP OF RETAINER. MIRU CODELL. POOH W/TBG. STING INTO RETAINER. RIH W/RETAINER TO 380'. MIRU CONSOLIDATED. PUMP 90SX CMT THROUGH RETAINER. MIRU CODELL. STING OUT OF RETAINER. MIRU CONSOLIDATED. PUMP 10SX CMT ON TOP OF RETAINER. MIRU CODELL. POOH W/TBG. MIRU CONSOLIDATED. PUMP 15SX CMT TO TOP OFF CSG

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed In No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded In Contoured In Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation In Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage In

Weeds present In Process Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: Well was plugged 6/14/17

Corrective Action: Cut, cap and cover wellhead. Remove equipment to begin final reclamation process Date 07/14/2017

Overall Final Reclamation In Process Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

**Pits:** ☒ NO SURFACE INDICATION OF PIT