

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/09/2017

Submitted Date:

06/14/2017

Document Number:

674300902**FIELD INSPECTION FORM**
 Loc ID 335678 Inspector Name: Spencer, Stan On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1600 BROADWAY ST STE 2600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|----------------------------|---------------------------------|
| Knudson, Dwayne | (970) 456-3335 | dknudson@ursaresources.com | All Inspections |
| Fischer, Alex | | alex.fischer@state.co.us | |
| Lujan, Carlos | | carlos.lujan@state.co.us | |
| Granahan, Kyle | | kyle.granahan@state.co.us | |

General Comment:

Site visit to assess management of potentially contaminated drill cuttings. Met with Ursa company man, Nate Gill. Cuttings are stockpiled on SW corner of pad. Cuttings not bermed but pad is bermed. Cuttings are dry and no indication of sediment runoff. No signs of petroleum contamination. One area of black material results from drilling through Cameo coal formation. Mr. Gill stated that no oil-based mud is being used. Cuttings sampling/analysis and subsequent management is subcontracted to HRL Compliance (Kris Rowe). If samples are < Table 910-1 concentrations, cuttings will be recycled for beneficial re-use. Otherwise material will be remediated or disposed per COGCC rules.

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------------------|---|
| 401308937 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4170767 |
| 674300903 | Cuttings stockpile looking south | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4170750 |
| 674300904 | coal fines in cuttings stockpile | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4170751 |