



photo 1: Facing southwest toward the former tank battery site.



photo 2: The gate at the fenced site is broken and need to be repaired.



photo 3: There are List B noxious weeds growing throughout the site.



photo 4: List B noxious weeds (Canada thistle). Seed heads are beginning to develop and disperse seed.



photo 5: There is undesirable vegetation growth at the site (Cheat grass, Kochia sp.)



photo 6: Facing west toward the surrounding undisturbed pasture.