



photo 1: One of the two entrances from highway 79. Two metal post remain at end on culvert.



photo 2: The culvert at the beginning of the access road has not been removed.



photo 3: Facing north at the former tank battery site.



photo 4: The crop growth has not adequately established at the former tank battery site. The 3.5' shovel indicates crop height.



photo 5: There is gravel that remains at the former tank battery site.



photo 6: Facing south toward the former tank battery site.



photo 7: Facing east toward the well site. The crop has not re-established in this area (approx. 60'x30').



photo 8: Facing toward the surrounding crop growth. The 3.5' shovel indicates crop height.