

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/21/2017

Submitted Date:

06/21/2017

Document Number:

674200119**FIELD INSPECTION FORM**

Loc ID 434375	Inspector Name: Gomez, Jason	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 4 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>10633</u> Name of Operator: <u>CRESTONE PEAK RESOURCES OPERATING LLC</u> Address: <u>1801 CALIFORNIA STREET #2500</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc.inspections@crestonepr.com	
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434369	WELL	DG	04/25/2017	LO	123-38121	Waste Connections 3B-29H-M168	DG
434370	WELL	DG	04/24/2017	LO	123-38122	Waste Connections 3A-29H-M168	DG
434371	WELL	DG	04/28/2017	LO	123-38123	Waste Connections 3D-29H-M168	DG
434372	WELL	DG	04/26/2017	LO	123-38124	Waste Connections 3C-29H-M168	DG
434373	WELL	DG	04/29/2017	LO	123-38125	Waste Connections 3E-29H-M168	DG
434374	WELL	DG	04/30/2017	LO	123-38126	Waste Connections 3G-29H-M168	DG
434378	WELL	DG	04/29/2017	LO	123-38129	Waste Connections 3F-29H-M168	DG

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type:

#

Comment: [Approx 32' sound walls on location used for sound mitigation](#)

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: [Mud cooling unit used for odor mitigation](#)

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Field Flare

Comment: [Not in use at time of inspection](#)

Corrective Action:

Date:

Inspected Facilities

Facility ID: <u>434369</u>	Type: <u>WELL</u>	API Number: <u>123-38121</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434370</u>	Type: <u>WELL</u>	API Number: <u>123-38122</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434371</u>	Type: <u>WELL</u>	API Number: <u>123-38123</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434372</u>	Type: <u>WELL</u>	API Number: <u>123-38124</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434373</u>	Type: <u>WELL</u>	API Number: <u>123-38125</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>434374</u>	Type: <u>WELL</u>	API Number: <u>123-38126</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>

ComplaintComment: Complaint Received June 20 & 21, 2017Field Inspector Assigned: Jason E. GomezComplaint Received:Date: 6-20 & 21--2017 TimeContacted by Complaint Specialist per Complaint Response formsDate: 6-21 -2017Well Number#: Location #: 434375Inspection Document #: 674200119Nature of complaint: OdorField Inspector Actions:

On 6/21/2017, I was contacted by complaint specialist Megan Adamczyk in reference to several complaints received by the COGCC about odor occurring in the Erie area south of the Crestone Peak Resources, Waste Connection drilling pad.

On 6-21-2017, I performed a complete site inspection of the Waste Connection location and the neighborhoods south and southeast of the drilling pad. At the time of inspection, I observed Ensign drilling rig 153 on the location performing drilling operation for Crestone Peak Resources. I reviewed location records, which did not show any abnormal drilling conditions at the time of the complaints. As part of my inspection I performed a sweep of the area of the complaints in an attempt to locate any odors off location. At no time during this inspection did I detect any odors off location.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

No violations of COGCC rules were observed at the time of the inspection.

Corrective Action:

Date:

Well Drilling

Rig: Rig Name: Ensign 153 Pusher/Rig Manager: Carlos Santos
 Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram:	<u>YES</u>	Blind Ram:	<u>YES</u>	Hydril Type:	<u>YES</u>
Pressure Test BOP:	<u>Pass</u>	Test Pressure PSI:	<u> </u>	Safety Plan:	<u>YES</u>
<u>Drill Fluids Management:</u>					
Lined Pit:	<u> </u>	Unlined Pit:	<u> </u>	Closed Loop:	<u> </u>
Multi-Well:	<u>YES</u>	Disposal Location:	<u> </u>		
<u>Comment:</u>	<div style="border: 1px solid black; height: 20px;"></div>				
Corrective Action:	<div style="border: 1px solid black; height: 20px;"></div>				Date:
Facility ID:	<u>434378</u>	Type:	<u>WELL</u>	API Number:	<u>123-38129</u>
Status:	<u>DG</u>	Insp. Status:	<u>DG</u>		

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment: not in use at time of inspection

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
		Waddles	Pass	Vehicle Tracking	Pass	
Gravel	Pass	Gravel	Pass	Covering Materials	Pass	

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT