

Inspection Photos

Location Number: 327385



Photo 1 Wellhead surrounded by crop from north



Photo 2 Separator from north

Inspection Photos



Photo 3 Emission Control Burner from south



Photo 4 Battery from south