



photo 1: Facing east toward the access road. Gravel remains along the road.



photo 2: Facing southeast toward the location.



photo 3: There are cement blocks that remain at the south side of the location.



photo 4: Facing north toward the location.



photo 5: There are noxious weeds (Canada thistle) along the northeastern side of the location.



photo 6: Facing south toward the surrounding crop field.