



**photo 1:** Facing north toward the access road.



**photo 2:** Center of thye location facing east toward the well site.





**photo 3:** Facing toward the east side of the location.



**photo 4:** There is pieces of lumber and pipe that remain at the east side of the location.





**photo 5:** East side of the location facing west.



**photo 6:** West side of the location facing east.