



photo 1: Facing southwest along the access road.



photo 2: Facing west toward the location.



photo 3: West side of the location facing northeast.



photo 4: South side of the location facing north.



photo 5: There are noxious weeds (Canada thistle) along the southeastern side of the location.



photo 6: Southeast side of the location facing northwest.