

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2017

Submitted Date:

06/26/2017

Document Number:

674704077

**FIELD INSPECTION FORM**

Loc ID 334768 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 19 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-263-2760	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288189	WELL	PR	12/05/2006	GW	045-13171	HOAGLUND PA 331-2	PR
288313	WELL	PR	08/20/2007	GW	045-13215	HOAGLUND PA 341-2	PR
288314	WELL	PR	08/20/2007	GW	045-13214	HOAGLUND PA 41-2	PR
288315	WELL	PR	12/11/2006	GW	045-13213	HOAGLUND PA 31-2	PR
288316	WELL	PR	12/11/2006	GW	045-13212	HOAGLUND PA 431-2	PR
288317	WELL	PR	08/20/2007	GW	045-13211	HOAGLUND PA 441-2	PR
288318	WELL	PR	12/11/2006	GW	045-13210	HOAGLUND PA 531-2	PR
288319	WELL	PR	08/20/2007	GW	045-13209	HOAGLUND PA 541-2	PR
288320	WELL	PR	12/11/2006	GW	045-13208	HOAGLUND PA 342-2	PR
288321	WELL	PR	08/20/2007	GW	045-13207	HOAGLUND PA 42-2	PR
288322	WELL	PR	12/11/2006	GW	045-13206	HOAGLUND PA 332-2	PR
288323	WELL	PR	12/11/2006	GW	045-13205	HOAGLUND PA 32-2	PR
288324	WELL	PR	08/21/2007	GW	045-13204	HOAGLUND PA 542-2	PR
288325	WELL	PR	08/20/2007	GW	045-13203	HOAGLUND PA 532-2	PR
288326	WELL	PR	08/20/2007	GW	045-13202	HOAGLUND PA 432-2	PR
288327	WELL	PR	08/20/2007	GW	045-13201	HOAGLUND PA 442-2	PR

**General Comment:**

2017 Flowline NTO Inspection 1000' Buffer  
Shadowing Operator Pressure Testing Team

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	970-285-9377	Date:	
Corrective Action:			

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Flow Line	# 1		corrective date
Comment:	Not in use: 2" line from tanks to separators. Witness pressure test of line. 68 psi for 15 mins.		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 288189 Type: WELL API Number: 045-13171 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Flowline**

#1	Type:	of Lines	
----	-------	----------	--

Flowline Description

Flowline Type:	Size:	Material:
Variance:	Age:	Contents:

Integrity Summary

Failures:	Spills:	Repairs Made:
Coatings:	H2S:	Cathodic Protection:

Pressure Testing

Witnessed:	Test Result:	Charted:
------------	--------------	----------

COGCC Rules(check all that apply)

1101. Installation and Reclamation     1102. Operations, Maintenance, and Repair     1103. Abandonment

Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 288313 Type: WELL API Number: 045-13215 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 288314 Type: WELL API Number: 045-13214 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 288315 Type: WELL API Number: 045-13213 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 288316 Type: WELL API Number: 045-13212 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 288317 Type: WELL API Number: 045-13211 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 288318 Type: WELL API Number: 045-13210 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 288319 Type: WELL API Number: 045-13209 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 288320 Type: WELL API Number: 045-13208 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 288321 Type: WELL API Number: 045-13207 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 288322 Type: WELL API Number: 045-13206 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 288323 Type: WELL API Number: 045-13205 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 288324 Type: WELL API Number: 045-13204 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 288325    Type: WELL    API Number: 045-13203    Status: PR    Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 288326    Type: WELL    API Number: 045-13202    Status: PR    Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 288327    Type: WELL    API Number: 045-13201    Status: PR    Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:

Date: