

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/19/2017

Submitted Date:

06/21/2017

Document Number:

682600323**FIELD INSPECTION FORM**

Loc ID 309599 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 16910Name of Operator: CHURCHILL ENERGY INCAddress: 8177 SOUTH NORFOLK STREETCity: ENGLEWOOD State: CO Zip: 80112**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Love, Kimerly J.	(303) 987-0241	kjlklcar@aol.com	
Kluksdahl, Gary	(303) 840-7000, (303) 618-5025	gary.kluksdahl@comcast.net	
Axelson, John		john.axelson@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218178	WELL	PR	09/12/2013	OW	073-06163	CHAMPLIN-LIMON 2-19	EI

**General Comment:**

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.



**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Spill/Remediation:**

Comment: [A release of fluid off the south side of the well pad is visible from in person inspection and historic aerial photography. See attached photos](#)

Corrective Action: [Operator shall submit Form 27 remediation to address release of fluid off south side of well pad.](#) Date: 07/21/2017

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<a href="#">Operator shall submit Form 27 remediation plan for closure of skim pit and drilling pit on location 309598 (Champlin Limon 1-19 well) and release off fluids off well pads on location 309598 (Champlin Limon 1-19 well) and location 309599 (Champlin Limon 2-19 well). Operator shall delineate horizontal and vertical extent of releases and shall remediate any impact(s) to groundwater or soil.</a>	kosolaj	06/21/2017
<a href="#">Operator shall submit Form 27 to area Environmental Protection Specialist by July 21, 2017.</a>		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401314070	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175963">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175963</a>
682600325	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175961">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175961</a>