

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/28/2017

Submitted Date:

06/28/2017

Document Number:

674005425**FIELD INSPECTION FORM**

Loc ID 440858 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1801 BROADWAY #500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	<a href="#">All Inspections</a>
Adamczyk, Megan		megan.adamczyk@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Precup, Jim		james.precup@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449252	WELL	DG	03/24/2017		123-44218	Simpson FD 16-379HC	DG

**General Comment:**

**Inspected Facilities**

Facility ID: 449252 Type: WELL API Number: 123-44218 Status: DG Insp. Status: DG

**Complaint**

Comment:

Complaint #: 200443097

Inspection Document # 674005425

Complainant Name: Daniel Buyck

Phone: 970 689 2662

Address: 562 Cherryridge Drive. Windsor, CO

Nature of complaint (sound, noise, etc): Noise

Inspection details:

Company representative on location: Brad Stevens  
 Visited with Scot Donato

Weather conditions:

Wind Calm, Temperature 71 degrees F

Sound meter location: 40.48681, -104.87337

Set up approximately 25 ft from residence in the direction of noise source (generators)

LEQ C Scale 77.2 db

Corrective Action:

Comply with noise regulations established in Rule 802 and further restricted in Rule 604.c.(2)A when the location is within a designated setback location. (NOTE: THIS IS COMPLAINT DRIVEN).

Date: 06/30/2017**Well Drilling**Rig: Rig Name: Precision Pusher/Rig Manager: \_\_\_\_\_Permit Posted: Yes Access Sign: Yes**Well Control Equipment:**Pipe Ram: YES Blind Ram: YES Hydril Type: \_\_\_\_\_

Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_

Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment

User

Date

Action required associated with noise complaint.  
 See inspection dated 6/27/2017 for location details.

carlilec

06/28/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674005426	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183895">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183895</a>
674005427	Sound Survey	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183896">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183896</a>
674005428	Inspection Details	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183897">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183897</a>