

Inspection Photos

6/28/2017

Operator: PDC ENERGY INC - 69175

Location ID: 323261

Inspection Doc. Number: 682502354

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 323261



Photo 1: Photo taken from well location, facing west. Photo shows well site remains bare and exposed soil.



Photo 2: Photo taken the well site, facing north. Photo shows access road has not been reclaimed. Gravel and ruts remain, road has not been revegetated. Access road ends at well location.

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 323261



Photo 3: Photo taken from the battery location, north of well, facing south. Photo shows cattle guard and access road have not been reclaimed.



Photo 4: Photo taken from the northeast end of the battery location, facing southwest. Photo shows tank battery location has not been reclaimed. Adjacent reference area is irrigated hay fields.

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 323261




Photo 5: 2014 aerial imagery. Photo shows well and battery location prior to plugging and abandonment.




Photo 6: Current, 2016 aerial imagery. Photo shows well and battery location post plugging and abandonment. With exception to the removal of equipment and facilities, very little reclamation work appears to have been conducted since the PA date of 11/15/2015