

Inspection Photos

6/28/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 430652

Inspection Doc. Number: 682502356

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 430652



Photo 1: Photo taken from the well location, facing east. Photo shows equipment has been removed. A follow-up inspection will need to be conducted when crop is growing to determine compliance with COGCC 1000 series reclamation rules.