

Inspection Photos – NTO Pressure testing  
Location Name: Willow Flowline  
Facility ID: 316372



Photo 1. Gauge at beginning of test. 292.8 psi.



Photo 2. Gauge after 15 minute test. 293.3 psi.