

Inspection Photos – NTO Pressure testing  
Location Name: 6" gathering line/Ryan's  
Gulch  
Facility ID: 451016



Photo 1. Gauge at beginning of test. 119.6 psi.



Photo 2. Gauge after 15 minute test. 119.5 psi.