

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/22/2017

Submitted Date:

06/22/2017

Document Number:

674005403

### FIELD INSPECTION FORM

Loc ID 307121 Inspector Name: Carlile, Craig On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 95233  
 Name of Operator: WELLINGTON OPERATING COMPANY  
 Address: 6065 S QUEBEC ST STE 200  
 City: CENTENNIAL State: CO Zip: 80111

**Findings:**

4 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Pomeroy, Bradley	303-220-5399	pomoco@msn.com	owner

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216911	WELL	PR	08/01/2008	OW	069-06098	WELLINGTON MUDDY UNIT 5-3	PR

**General Comment:**

[2017 Flowline NTO Inspection 1000' Buffer Shadowing Operator Pressure Testing Team](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Pipe		
Corrective Action:		Date:	

**Equipment:**

					corrective date
Type: Pump Jack	# 1				
Comment:					
Corrective Action:		Date:			

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 216911 Type: WELL API Number: 069-06098 Status: PR Insp. Status: PR**COGCC Comments**

Comment	User	Date
Pressure test Chart to be submitted separatley. Pressure test duration 15 minutes. Start of test at 65 PSI After 15 minutes 61 PSI	carlilec	06/22/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401317030	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4178662">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4178662</a>
674005404	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4178651">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4178651</a>