

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2017

Submitted Date:

06/26/2017

Document Number:

674704077**FIELD INSPECTION FORM**

Loc ID 334768	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 19 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
------------------	------------------------------------	---	-------------------	---

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-263-2760	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288189	WELL	PR	12/05/2006	GW	045-13171	HOAGLUND PA 331-2	PR
288313	WELL	PR	08/20/2007	GW	045-13215	HOAGLUND PA 341-2	PR
288314	WELL	PR	08/20/2007	GW	045-13214	HOAGLUND PA 41-2	PR
288315	WELL	PR	12/11/2006	GW	045-13213	HOAGLUND PA 31-2	PR
288316	WELL	PR	12/11/2006	GW	045-13212	HOAGLUND PA 431-2	PR
288317	WELL	PR	08/20/2007	GW	045-13211	HOAGLUND PA 441-2	PR
288318	WELL	PR	12/11/2006	GW	045-13210	HOAGLUND PA 531-2	PR
288319	WELL	PR	08/20/2007	GW	045-13209	HOAGLUND PA 541-2	PR
288320	WELL	PR	12/11/2006	GW	045-13208	HOAGLUND PA 342-2	PR
288321	WELL	PR	08/20/2007	GW	045-13207	HOAGLUND PA 42-2	PR
288322	WELL	PR	12/11/2006	GW	045-13206	HOAGLUND PA 332-2	PR
288323	WELL	PR	12/11/2006	GW	045-13205	HOAGLUND PA 32-2	PR
288324	WELL	PR	08/21/2007	GW	045-13204	HOAGLUND PA 542-2	PR
288325	WELL	PR	08/20/2007	GW	045-13203	HOAGLUND PA 532-2	PR
288326	WELL	PR	08/20/2007	GW	045-13202	HOAGLUND PA 432-2	PR
288327	WELL	PR	08/20/2007	GW	045-13201	HOAGLUND PA 442-2	PR

General Comment:2017 Flowline NTO Inspection 1000' Buffer
Shadowing Operator Pressure Testing Team

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Flow Line	# 1		corrective date
Comment:	Not in use: 2" line from tanks to separators. Witness pressure test of line. 68 psi for 15 mins.		
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 288189	Type: WELL	API Number: 045-13171	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		
Flowline				
#1	Type:	of Lines		
<u>Flowline Description</u>				
Flowline Type:		Size:	Material:	
Variance:		Age:	Contents:	
<u>Integrity Summary</u>				
Failures:		Spills:	Repairs Made:	
Coatings:		H2S:	Cathodic Protection:	
<u>Pressure Testing</u>				
Witnessed:		Test Result:	Charted:	
<u>COGCC Rules(check all that apply)</u>				
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input type="checkbox"/> 1103. Abandonment				
Comment:				
Corrective Action:		Date:		
Facility ID: 288313	Type: WELL	API Number: 045-13215	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 288314	Type: WELL	API Number: 045-13214	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 288315	Type: WELL	API Number: 045-13213	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 288316	Type: WELL	API Number: 045-13212	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		

Facility ID:	288317	Type:	WELL	API Number:	045-13211	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288318	Type:	WELL	API Number:	045-13210	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288319	Type:	WELL	API Number:	045-13209	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288320	Type:	WELL	API Number:	045-13208	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288321	Type:	WELL	API Number:	045-13207	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288322	Type:	WELL	API Number:	045-13206	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288323	Type:	WELL	API Number:	045-13205	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288324	Type:	WELL	API Number:	045-13204	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	288325	Type:	WELL	API Number:	045-13203	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	288326	Type:	WELL	API Number:	045-13202	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	288327	Type:	WELL	API Number:	045-13201	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401319014	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4180646