



**photo 1:** Facing west toward the site. There is inadequate crop growth within this area approximately 25'x10' in size.




**photo 2:** Facing back toward the east at the site.





**photo 3:** There is gravel that remains where crop growth has not re-established.



**photo 4:** Facing west toward the surrounding crop growth.