

Inspection Photos – NTO Pressure testing

Location Name: 6" Gas Line

Facility ID: 451236



Photo 1. Gauge at beginning of test. 137.2 psi.



Photo 2. Gauge after 15 minute test. 137 psi.