

Inspection Photos
Location Name: Bruton 30-10 Pad
Location ID: 418985



Photo 1. Fence has been repaired and is in good condition.