

Photo#1:

Overview of Location to South West shows extent of Reclamation work..



June 29, 2017

## Photo#2:

View SW of newly contoured Cut Slope.



June 29, 2017



Photo#3:

View West down Fill Slope to BMPs installed at Base.



June 29, 2017