



**Inspected Facilities**

Facility ID: 449252 Type: WELL API Number: 123-44218 Status: DG Insp. Status: DG

**Complaint**

Comment:

Complaint #: 200443097  
 Inspection Document # 674005425  
 Complainant Name: Daniel Buyck  
 Phone: 970 689 2662  
 Address: 562 Cherryridge Drive. Windsor, CO  
 Nature of complaint (sound, noise, etc): Noise  
 Inspection details:  
 Company representative on location: Brad Stevens  
 Visited with Scot Donato  
 Weather conditions:  
 Wind Calm, Temperature 71 degrees F  
 Sound meter location: 40.48681, -104.87337  
 Set up approximately 25 ft from residence in the direction of noise source (generators)  
 LEQ C Scale 77.2 db

Corrective Action:

Comply with noise regulations established in Rule 802 and further restricted in Rule 604.c.(2)A when the location is within a designated setback location. (NOTE: THIS IS COMPLAINT DRIVEN).

Date: 06/30/2017

**Well Drilling**

**Rig:** Rig Name: Precision Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: Yes Access Sign: Yes

**Well Control Equipment:**

Pipe Ram: YES Blind Ram: YES Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES

**Drill Fluids**

**Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
Action required associated with noise complaint. See inspection dated 6/27/2017 for location details.	carlilec	06/28/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401323670	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183899">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183899</a>
674005426	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183895">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183895</a>
674005427	Sound Survey	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183896">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183896</a>
674005428	Inspection Details	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183897">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183897</a>