

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401331775

Date Received:
07/05/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 5 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10630

Name of Operator: ALTA MESA SERVICES LP

Address: 15021 KATY FREEWAY SUITE 400

City: HOUSTON State: TX Zip: 77094

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

JAMESON MAX

281-944-0638

mjameson@altamesa.net

Housey, Melissa

melissa.housey@state.co.us

JOHNSON JERRY

361-230-5151

jjohnson@altamesa.net

KASSAB DIANE

dkassab@altamesa.net

Adamczyk, Megan

megan.adamczyk@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 673504439

Inspection Date: 06/12/2017

FIR Submit Date: 06/13/2017

FIR Status: _____

Inspected Operator Information:

Company Name: ALTA MESA SERVICES LP

Company Number: 10630

Address: 15021 KATY FREEWAY SUITE 400

City: HOUSTON State: TX Zip: 77094

LOCATION - Location ID: 429618

Location Name: Freeman Number: 3-24 County: HUERFANO

Qtrqr: NWS Sec: 24 Twp: 27S Range: 69W Meridian: 6
W

Latitude: 37.684828 Longitude: -105.067631

FACILITY - API Number: 05-055- -00 Facility ID: 429619

Facility Name: Freeman Number: 3-24

Qtrqr: NWS Sec: 24 Twp: 27S Range: 69W Meridian: 6
W

Latitude: 37.684828 Longitude: -105.067631

CORRECTIVE ACTIONS:

1 CA# 81622

Corrective Action: Comply with Rule 603.f. Remove unused equipment.

Date: 06/22/2017

Response: CA COMPLETED

Date of Completion: 07/05/2017

Operator
Comment:

1. A Sundry Notice Form 4 (Document No. 401331736) was submitted on 7/05/2017 to request delayed interim reclamation. The reclamation will be performed after the completion activities are finished as detailed on the Form 4.
2. The unused equipment are the components of the temporary land tank that needs to be assembled to contain the frac water. It will be erected once a minimum volume of water is supplied to hold the plastic liner in place and build the metal outer wall around it.

COGCC Decision: _____

COGCC
Representative:

--

4 CA# 81625

Corrective Action: Perform Interim reclamation and reduce the size of the location as specified in the 2A.

Date: 06/12/2014

Response: CA COMPLETED

Date of Completion: 07/05/2017

Operator
Comment:

A Sundry Notice Form 4 (Document No. 401331736) was submitted on 7/05/2017 to request delayed interim reclamation. The reclamation will be performed after the completion activities are finished as detailed on the Form 4.

COGCC Decision: _____

COGCC
Representative:

--

OPERATOR COMMENT AND SUBMITTAL

Comment: CA# 81623 and CA# 81626 have been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Max Jameson

Signed: _____

Title: Regulatory Coordinator

Date: 7/5/2017 9:39:30 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files