



Photo 1: View of riser at 37.55895, -108.86662, along access road.



Photo 2: View of a second riser at 37.55887, -108.86509, at entrance to access road.



Photo 3: View of a third riser at 37.55893, -108.86489, across from entrance to access road.



Photo 4: View of the western portion of the project area from the southwestern corner facing northward. Well pad is not recontoured. Vegetation is established and mowed. What appears to be surface owner equipment is stored in this portion of the well pad area.



Photo 5: View of the project area from the southwestern corner facing center.



Photo 6: View of the southern portion of the project area from the southwestern corner facing eastward.