

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/05/2017

Submitted Date:

07/05/2017

Document Number:

679902710**FIELD INSPECTION FORM**

Loc ID 305021 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 16000 DALLAS PARKWAY #875City: DALLAS State: TX Zip: 75248-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Grant, Rachael	918-585-1650 ext 212	regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277632	WELL	PR	08/05/2005	GW	125-09267	ENGEL 22-5	PR

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Dirt road through pasture		
Corrective Action:		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Metal panels around unit, wellhead and meter run		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator 50% buried by meter run		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Jensen unit		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Telemetry equipment and gas scrubber		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Kohler gas engine		
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	277632	Type:	WELL	API Number:	125-09267	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment: Access has erosion near wellhead that needs maintenance. Access has erosion at the incline to location. Check dams lack maintenance and erosion has carried sediments off of access into pasture at the steep incline. Repair and maintain access. Repair and maintain BMPs. Install additional BMPs if necessary

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT