

Inspection Photos

7/11/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 329457

Inspection Doc. Number: 682502387

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 329457



Photo 1: Photo taken from the battery location, facing west. Photo shows facilities have been removed.



Photo 2: Photo taken from the well location, facing north. Photo shows crop at the well location. Crop does not appear to be establishing uniformly compared to that of the reference.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 329457



Photo 3: Photo taken from the well location. Photo shows crop on the disturbance area shown here is ~4 feet in height (6 foot measuring stick)



Photo 4: Photo taken from the well location. Photo shows crop on the reference area shown here is ~6 feet in height (6 foot measuring stick).