

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/05/2017

Submitted Date:

07/12/2017

Document Number:

666803342**FIELD INSPECTION FORM**

Loc ID 335490	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				<b>Findings:</b> <u>20</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	<a href="#">Field Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298653	WELL	PR	04/28/2011	GW	045-17309	SAVAGE RWF 443-26	PR
298654	WELL	PR	09/30/2010	GW	045-17310	SAVAGE RWF 542-26	PR
298655	WELL	PR	06/30/2010	GW	045-17311	SAVAGE RWF 442-26	PR
298656	WELL	PR	06/01/2011	GW	045-17312	SAVAGE RWF 342-26	PR
298677	WELL	PR	08/31/2010	GW	045-17324	SAVAGE RWF 42-26	PR
298678	WELL	PR	03/11/2011	GW	045-17325	SAVAGE RWF 541-26	PR
298679	WELL	PR	09/30/2010	GW	045-17326	SAVAGE RWF 441-26	PR
298680	WELL	PR	11/15/2010	GW	045-17327	SAVAGE RWF 341-26	PR
298681	WELL	PR	10/31/2010	GW	045-17328	SAVAGE RWF 41-26	PR
298682	WELL	PR	06/01/2011	GW	045-17329	SAVAGE RWF 33-26	PR
298683	WELL	PR	08/31/2010	GW	045-17330	SAVAGE RWF 532-26	PR
298684	WELL	PR	09/30/2010	GW	045-17331	SAVAGE RWF 432-26	PR
298685	WELL	PR	09/30/2010	GW	045-17332	SAVAGE RWF 332-26	PR
298686	WELL	PR	09/30/2010	GW	045-17333	SAVAGE RWF 32-26	PR
298687	WELL	PR	10/31/2010	GW	045-17334	SAVAGE RWF 531-26	PR
298688	WELL	PR	10/31/2010	GW	045-17335	SAVAGE RWF431-26	PR
298689	WELL	PR	10/31/2010	GW	045-17336	SAVAGE RWF 331-26	PR
298690	WELL	PR	03/11/2011	GW	045-17337	SAVAGE RWF 31-26	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

# 18

Comment: Corrective Action: Date: 

Type: Ancillary equipment

# 4

Comment: Chemical units at wellhead

Corrective Action: Date: 

Type: Horizontal Heated Separator

# 18

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	200 BBLs	STEEL AST		39.499038,-107.850725	
Comment: <input type="text"/>						
Corrective Action: <input type="text"/>					Date: <input type="text"/>	

**Paint**Condition Adequate Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <input type="text"/>				
Corrective Action: <input type="text"/>				Date: <input type="text"/>

**Venting:**

Yes/No NO

Comment:

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	298653	Type:	WELL	API Number:	045-17309	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298654	Type:	WELL	API Number:	045-17310	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298655	Type:	WELL	API Number:	045-17311	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298656	Type:	WELL	API Number:	045-17312	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298677	Type:	WELL	API Number:	045-17324	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298678	Type:	WELL	API Number:	045-17325	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298679	Type:	WELL	API Number:	045-17326	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298680	Type:	WELL	API Number:	045-17327	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	298681	Type:	WELL	API Number:	045-17328	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298682	Type:	WELL	API Number:	045-17329	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298683	Type:	WELL	API Number:	045-17330	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298684	Type:	WELL	API Number:	045-17331	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298685	Type:	WELL	API Number:	045-17332	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298686	Type:	WELL	API Number:	045-17333	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298687	Type:	WELL	API Number:	045-17334	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298688	Type:	WELL	API Number:	045-17335	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	298689	Type:	WELL	API Number:	045-17336	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	298690	Type:	WELL	API Number:	045-17337	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Culverts	Pass			
Seeding	In Process					
Ditches	Pass					
		Ditches	Pass			
Berms	Pass					
Sediment Traps	Pass					
		Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT