

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/06/2017

Submitted Date:

07/12/2017

Document Number:

666803344**FIELD INSPECTION FORM**Loc ID 335478 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296693	WELL	PR	05/20/2009	GW	045-16101	SAVAGE RWF 411-26	PR
297596	WELL	PR	02/12/2009	GW	045-16885	SAVAGE RWF 12-26	PR
297597	WELL	PR	05/20/2009	GW	045-16886	SAVAGE RMV 149-26	PR
297598	WELL	PR	02/28/2009	GW	045-16887	SAVAGE RWF 21-26	PR
297672	WELL	PR	08/12/2008	GW	045-16914	SAVAGE RWF 321-26	PR
297673	WELL	PR	05/31/2009	GW	045-16915	SAVAGE RWF 322-26	PR
297674	WELL	PR	08/12/2008	GW	045-16916	SAVAGE RWF 412-26	PR
297675	WELL	PR	05/31/2009	GW	045-16917	SAVAGE RWF 323-26	PR
297676	WELL	PR	05/31/2009	GW	045-16918	SAVAGE RWF 522-26	PR
297677	WELL	PR	08/12/2008	GW	045-16919	SAVAGE RWF 421-26	PR
297678	WELL	PR	08/12/2008	GW	045-16920	SAVAGE RWF 22-26	PR
297679	WELL	PR	08/12/2008	GW	045-16921	SAVAGE RWF 312-26	PR
297680	WELL	PR	08/12/2008	GW	045-16922	SAVAGE RWF 13-26	PR
297681	WELL	PR	08/12/2008	GW	045-16923	SAVAGE RWF 422-26	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

14

Comment:

Corrective Action:

Date:

Type: Emission Control Device

1

Comment: [Disconnected](#)

Corrective Action:

Date:

Type: Ancillary equipment

4

Comment: [Chemical units at wellhead](#)

Corrective Action:

Date:

Type: Plunger Lift

14

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST		39.497123,-107.859258

Comment:

Corrective Action:

Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	296693	Type:	WELL	API Number:	045-16101	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	297596	Type:	WELL	API Number:	045-16885	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	297597	Type:	WELL	API Number:	045-16886	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	297598	Type:	WELL	API Number:	045-16887	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	297672	Type:	WELL	API Number:	045-16914	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	297673	Type:	WELL	API Number:	045-16915	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	297674	Type:	WELL	API Number:	045-16916	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	297675	Type:	WELL	API Number:	045-16917	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	297676	Type:	WELL	API Number:	045-16918	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	297677	Type:	WELL	API Number:	045-16919	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	297678	Type:	WELL	API Number:	045-16920	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	297679	Type:	WELL	API Number:	045-16921	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	297680	Type:	WELL	API Number:	045-16922	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	297681	Type:	WELL	API Number:	045-16923	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	Disconnected
Pilot: OFF	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Gravel	Pass					
		Culverts	Pass			
Seeding	In Process					
		Ditches	Pass			
		Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT