

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/06/2017

Submitted Date:

07/12/2017

Document Number:

666803347**FIELD INSPECTION FORM**

Loc ID 335488 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298067	WELL	PR	01/31/2010	GW	045-17050	SAVAGE RWF 544-26	PR
298068	WELL	PR	02/26/2009	GW	045-17052	SAVAGE RWF 543-26	PR
298069	WELL	PR	12/31/2009	GW	045-17053	SAVAGE RWF 343-26	PR
298070	WELL	PR	12/31/2009	GW	045-17054	SAVAGE RWF 43-26	PR
298071	WELL	PR	01/31/2010	GW	045-17055	SAVAGE RWF 434-26	PR
298072	WELL	PR	01/31/2010	GW	045-17056	SAVAGE RWF 34-26	PR
298073	WELL	PR	01/31/2010	GW	045-17057	SAVAGE RWF 533-26	PR
298074	WELL	PR	12/31/2009	GW	045-17058	SAVAGE RMV 47-26	PR
298075	WELL	PR	01/11/2010	GW	045-17059	SAVAGE RWF 433-26	PR
298076	WELL	PR	01/31/2010	GW	045-17060	SAVAGE RWF 344-26	PR
298077	WELL	PR	04/16/2011	GW	045-17061	SAVAGE RWF 44-26	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

11

Comment: Corrective Action: Date:

Type: Ancillary equipment

2

Comment: Chemical units at wellhead

Corrective Action: Date:

Type: Horizontal Heated Separator

11

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		39.491593,-107.850441	
Comment: <input type="text"/>						
Corrective Action: <input type="text"/>						
Date: <input type="text"/>						

Paint

Condition Adequate

Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment: <input type="text"/>				
Corrective Action: <input type="text"/>				
Date: <input type="text"/>				

Venting:

Yes/No NO

Comment:

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID:	298067	Type:	WELL	API Number: 045-17050 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:				Date:
Facility ID:	298068	Type:	WELL	API Number: 045-17052 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:				Date:
Facility ID:	298069	Type:	WELL	API Number: 045-17053 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:				Date:
Facility ID:	298070	Type:	WELL	API Number: 045-17054 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:				Date:
Facility ID:	298071	Type:	WELL	API Number: 045-17055 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:				Date:
Facility ID:	298072	Type:	WELL	API Number: 045-17056 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:				Date:
Facility ID:	298073	Type:	WELL	API Number: 045-17057 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:				Date:
Facility ID:	298074	Type:	WELL	API Number: 045-17058 Status: PR Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:				Date:

Facility ID:	298075	Type:	WELL	API Number:	045-17059	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	298076	Type:	WELL	API Number:	045-17060	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	298077	Type:	WELL	API Number:	045-17061	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Culverts	Pass			
		Ditches	Pass			
		Gravel	Pass			
Seeding	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT