

# Inspection Photos

7/12/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 327102

Inspection Doc. Number: 682502409

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 327102



**Photo 1:** Photo taken from the well location, facing west. Photo shows crop (corn) vegetation growth over the well location is stunted when compared to the adjacent reference area.

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 327102



**Photo 2:** Photo taken from the well location, facing west. Photo shows crop (corn) vegetation growth over the well location is stunted when compared to the adjacent reference area. 6 foot measuring stick for reference. Crop height over the disturbance area ranges from 2.5 to 3 feet in height.



**Photo 3:** Photo taken from the adjacent reference area. Photo shows crop (corn) vegetation growth over the adjacent reference area. 6 foot measuring stick for reference. Crop height over the adjacent reference area ranges from 4.5 to 5 feet in height

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 327102



**Photo 1:** Photo taken from the battery location, facing north. Photo shows crop (corn) vegetation growth over the battery location is stunted when compared to the adjacent reference area.

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 327102




**Photo 5:** Photo taken from the battery location, facing west. Photo shows crop (corn) vegetation growth over the well location is stunted when compared to the adjacent reference area. 6 foot measuring stick for reference. Crop height over the disturbance area ranges from 1 to 2.5 feet in height.



**Photo 6:** Photo taken from the adjacent reference area. Photo shows crop (corn) vegetation growth over the adjacent reference area. 6 foot measuring stick for reference. Crop height over the adjacent reference area ranges from 4.5 to 5 feet in height.

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 327102



**Photo 1:** Photo taken from the well location, facing north. Photo shows vegetation over the reclamation area. Note: noble pipeline recently constructed through well location, re-disturbing the site.